Ref #	Hits	Search Query	DBs ·	Default Operator	Plurals	Time Stamp
L1	0	shaft same fastener same tool and angle near rate near sensor and multimeter	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/29 12:59
L2		"5476014".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/29 13:01
L3	19	angle with rotation same hous\$4 same reference near point	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/29 13:03
L4	3	angle with rotation same reference near point and hous\$4 and multimeter	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/29 13:04
L5	186	angle with rotation same reference near point and hous\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/29 13:04
L6	7	angle with rotation same reference near point and hous\$4 and ratchet	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/29 13:09
L7	1745	angle with rotation and hous\$4 and ratchet	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/29 13:09
L8	986	angle with rotation and hous\$4 and ratchet and screw	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/29 13:10
L9	791	angle with rotation and hous\$4 and ratchet and screw and shaft	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/29 13:10
L10	0	angle with rotation and hous\$4 and ratchet and screw and shaft and beyond with reference with point	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/29 13:10
L11	66	angle with rotation and hous\$4 and ratchet and screw and shaft and reference with point	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/29 13:12
L12	34	angle with rotation and hous\$4 and ratchet and screw and shaft and beyond with point	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/29 13:13

L13	35	angle with rotation and hous\$4 and ratchet and screw and shaft and zero with point	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/29 13:13
L14	47	angle with rotation and hous\$4 and ratchet and (screw bolt nut fastener) and shaft and zero with point	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/29 13:14
L15	11	measur\$4 with angle with rotation and hous\$4 and ratchet and (screw bolt nut fastener) and shaft and zero with point	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/29 13:40
L16	6	"2914287"	US-PGPUB; USPAT; EPO	OR	ON ·	2005/03/29 13:36
L17	10	("2365419" "2734412" "2796674" "2889729" "4265109" "4608872").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/03/29 13:37
L18	11	("2007880" "2074079" "2300652" "2614418" "2756622" "4290329").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/03/29 13:44
L19	20	measur\$4 with angle with rotation and hous\$4 and (ratchet screwdriver wrench) and (screw bolt nut fastener) and shaft and zero with point	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/29 14:30
L20	3	("4589289").URPN.	USPAT	OR	OFF	2005/03/29 13:43
L21	. 0	"2914287".pn.	EPO	OR	ON	2005/03/29 13:45
L22	0	"2914287"	EPO	OR	ON	2005/03/29 13:45
L23	20	measur\$4 with angle with rotation and hous\$4 and (ratchet screwdriver wrench) and (screw bolt nut fastener) and shaft and zero with point and ad<="09282001"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/29 14:32